

**Royal Liverpool University Hospital**  
HTA licensing number 30002

Licensed under the Human Tissue Act 2004

**Licensed activities**

The table below shows the activities this establishment is licensed for and the activities currently undertaken at the establishment.

<b>Area</b>	<b>Making of a post-mortem examination</b>	<b>Removal from the body of a deceased person (otherwise than in the course of an anatomical examination or post-mortem examination) of relevant material of which the body consists or which it contains, for use for a scheduled purpose other than transplantation</b>	<b>Storage of the body of a deceased person or relevant material which has come from a human body for use for a scheduled purpose</b>
<b>Hub site</b> <b>Royal Liverpool Hospital</b>	Licensed	Licensed	Licensed
<b>Mortuary</b>	<i>Carried out</i>	<i>Carried out</i>	<i>Carried out</i>
<b>Pathology lab</b>	-	-	<i>Carried out</i>

**Summary of inspection findings**

The HTA found the Designated Individual (DI) and the Licence Holder (LH) to be suitable in accordance with the requirements of the legislation.

Although the HTA found that Royal Liverpool University Hospital ('the establishment') had met the majority of the HTA's standards, three major and seven minor shortfalls were found against standards for consent, governance and quality systems, traceability and premises, facilities and equipment.

The HTA has assessed the establishment as suitable to be licensed for the activities specified, subject to corrective and preventative actions being implemented to meet the shortfalls identified during the inspection.

### **Compliance with HTA standards**

#### ***Major shortfalls***

<b>Standard</b>	<b>Inspection findings</b>	<b>Level of shortfall</b>
<b>GQ1 All aspects of the establishment's work are governed by documented policies and procedures</b>		

<p>a) Documented policies and SOPs cover all mortuary/laboratory procedures relevant to the licensed activity, take account of relevant Health and Safety legislation and guidance and, where applicable, reflect guidance from RCPATH.</p>	<p>Standard Operating Procedures (SOPs) lack sufficient detail. Key steps are included but these do not specify the individual actions that need to be undertaken to accomplish each step. At the time of inspection, procedures observed by the inspection team were not consistent with that of the SOPs. These include, but are not limited to, SOPs detailing the process for:</p> <ul style="list-style-type: none"> <li>• Admission and condition checking.</li> <li>• Visiting and viewing of the deceased.</li> <li>• release; and</li> <li>• contingency storage arrangements</li> </ul> <p>This is not an exhaustive list of the SOPs requiring amendment. To fully address this shortfall the establishment should review all SOPs relating to mortuary activities to ensure that they are accurate and contain sufficient detail to reflect current practice.</p> <p>This shortfall was identified at the last inspection, and whilst addressed at the time, practices have again changed, and SOPs have not been updated.</p>	<p><b>Major</b></p>
<p><b>T1 A coding and records system facilitates traceability of bodies and human tissue, ensuring a robust audit trail</b></p>		
<p>c) Three identifiers are used to identify bodies and tissue, (for example post mortem number, name, date of birth/death), including at least one unique identifier</p>	<p>Visits out of working hours do not have a documented procedure and are completed by non-mortuary staff. The inspection team were not assured that three identifiers were used when preparing the body or meeting visitors.</p> <p>Furthermore, the bereavement team only requires visitors to provide one identifier of the body when they attend the mortuary for a viewing during working hours.</p> <p>This poses the risk of viewing of the wrong body and immediate actions were taken to address this shortfall before the inspection team left the site.</p>	<p><b>Major</b></p>

<b>PFE1 The premises are secure and well maintained and safeguard the dignity of the deceased and the integrity of human tissue.</b>		
e) Security arrangements protect against unauthorized access and ensure oversight of visitors and contractors who have a legitimate right of access	<p>A single swipe card is used by porters and the security team to access the mortuary. There is no traceability of who collects and returns this card, if they have received mortuary training, or have a legitimate reason to enter the mortuary.</p> <p>Although covered by CCTV, this is reviewed retrospectively and only if there is a reason to do so. This means mortuary staff do not have oversight, nor are able to effectively audit, the individual using the swipe card or the time of entry and exit to the restricted areas.</p>	<b>Major</b>

### **Minor Shortfalls**

<b>Standard</b>	<b>Inspection findings</b>	<b>Level of shortfall</b>
<b>C2 Staff involved in seeking consent receive training and support in the essential requirements of taking consent</b>		
b) Records demonstrate up-to-date staff training.	Staff seeking consent have received training, however this is out of date and is not formally refreshed on a regular basis.	<b>Minor</b>
d) Competency is assessed and maintained	Staff seeking consent ensure they have a competency assessment each time the taking of consent is required. However, this is not documented.	<b>Minor</b>

<b>GQ1 All aspects of the establishment's work are governed by documented policies and procedures</b>
---

c) Procedures on body storage prevent practices that disregard the dignity of the deceased	Whilst staff check the condition of the bodies, and act accordingly, this is not recorded in a consistent manner.  Mortuary staff are unable to provide traceability evidence for condition checks of all bodies within the mortuary.	<b>Minor</b>
<b>GQ2 There is a documented system of audit</b>		
b) Audit findings document who is responsible for follow-up actions and the timeframe for completing these	Audits identify areas of non-conformance. However, the audit forms used are inconsistent and do not always state required actions, persons responsible or a target timeframe of completion of actions.	<b>Minor</b>
<b>GQ6 Risk assessments of the establishment's practices and processes are completed regularly, recorded and monitored</b>		
b) Risk assessments include how to mitigate the identified risks. This includes actions that need to be taken, who is responsible for each action, deadlines for completing actions and confirmation that actions have been completed	Risk assessments are not consistent in the level of assessment of risk and detail of mitigations implemented.  Those for mortuary related activity require a more detailed assessment and documented persons responsible for the mitigation actions identified.	<b>Minor</b>
<b>PFE1 The premises are secure and well maintained and safeguard the dignity of the deceased and the integrity of human tissue.</b>		
a) The premises are clean and well maintained	The body store flooring has areas of damaged and deteriorated sealing. This presents a risk of ineffective decontamination.	<b>Minor</b>
<b>PFE3 Equipment is appropriate for use, maintained, validated and where appropriate monitored</b>		
a) Items of equipment in the mortuary are in good condition and appropriate for use	The viewing bier and one hydraulic trolley has a significant amount of rust. This presents a risk of ineffective decontamination.	<b>Minor</b>

The HTA requires the DI to submit a completed corrective and preventative action (CAPA) plan setting out how the shortfalls will be addressed, within 14 days of receipt of the final report (refer to Appendix 2 for recommended timeframes within which to complete actions). The HTA will then inform the establishment of the evidence required to demonstrate that the actions agreed in the plan have been completed.

### Advice

The HTA advises the DI to consider the following to further improve practice:

Number	Standard	Advice
1.	C1(a)	The DI is advised to prioritise the ratification of the new consent policy to ensure staff have access to the latest version.
2.	PFE1(a)	The DI is advised to monitor exposed metal work within the body store, to ensure it does not rust as this could result in a further shortfall of HTA standard PFE1(a).
3.	PFE2(e)	The mortuary team are advised to record the occasions when they are called out of hours for fridge alarms as a documented assurance that the procedure works.

### Background

Royal Liverpool University Hospital has been licensed by the HTA since October 2007. This was the fourth inspection of the establishment; the most recent previous inspection took place in May 2018.

Since the previous inspection, there has been a change to the corporate licence holder and designated individual. There have been no significant changes to the licensed activities.

## **Description of inspection activities undertaken**

The HTA's regulatory requirements are set out in Appendix 1. The inspection team covered the following areas during the inspection:

### *Standards assessed against during inspection*

71 out of the 72 standards were assessed. Standard PFE2(h) was not applicable as babies and infants are transferred to another licensed establishment.

### *Review of governance documentation*

The inspection included a review of the establishment's governance documentation relating to licensed activities. This included policies and procedural documents relating to licensed activities, cleaning records for the mortuary, records of servicing of equipment, ventilation reports, audits, risk assessments, meeting minutes, reported incidents and training records for both the mortuary staff and porters.

### *Visual inspection*

The inspection included a visual assessment of the establishment including, body storage areas, postmortem/preparation rooms, viewing rooms and tissue storage areas. The inspection team observed the processes for admission, release and viewing of bodies within the mortuary.

### *Audit of records*

Audits were conducted onsite of four bodies from refrigerated and frozen storage. Identification details on bodies were crosschecked against the information recorded in the register and associated paperwork. No discrepancies were identified.

Audits of traceability were conducted for tissue blocks and slides from four coronial consented cases. These included audits of the consent documentation, families wishes and the retention of these tissues. No discrepancies were identified.

### *Meetings with establishment staff*

Staff carrying out processes under the licence were interviewed including the DI, APT, pathologist, mortuary porter, and bereavement officer.

**Report sent to DI for factual accuracy: 19 December 2022**

**Report returned from DI: No factual accuracy or request for redaction comments were made by the DI**

**Final report issued: 06 January 2023**

**Completion of corrective and preventative actions (CAPA) plan**

Based on information provided, the HTA is satisfied that the establishment has completed the agreed actions in the CAPA plan and in doing so has taken sufficient action to correct all shortfalls addressed in the Inspection Report.

**Date: 15 August 2023**



## **Appendix 1: The HTA's regulatory requirements**

Prior to the grant of a licence, the HTA must assure itself that the DI is a suitable person to supervise the activity authorised by the licence and that the premises are suitable for the activity.

The statutory duties of the DI are set down in Section 18 of the Human Tissue Act 2004. They are to secure that:

- the other persons to whom the licence applies are suitable persons to participate in the carrying-on of the licensed activity;
- suitable practices are used in the course of carrying on that activity; and
- the conditions of the licence are complied with.

Its programme of inspections to assess compliance with HTA licensing standards is one of the assurance mechanisms used by the HTA.

The HTA developed its licensing standards with input from its stakeholders. They are designed to ensure the safe and ethical use of human tissue and the dignified and respectful treatment of the deceased. They are grouped under four headings:

- consent
- governance and quality systems
- traceability
- premises facilities and equipment.

This is an exception-based report: only those standards that have been assessed as not met are included. Where the HTA determines that there has been a shortfall against a standard, the level of the shortfall is classified as 'Critical', 'Major' or 'Minor' (see Appendix 2: Classification of the level of shortfall). Where HTA standards are fully met, but the HTA has identified an area of practice that could be further improved, advice is provided.

HTA inspection reports are published on the HTA's website.

## **Appendix 2: Classification of the level of shortfall**

Where the HTA determines that a licensing standard is not met, the improvements required will be stated and the level of the shortfall will be classified as 'Critical', 'Major' or 'Minor'. Where the HTA is not presented with evidence that an establishment meets the requirements of an expected standard, it works on the premise that a lack of evidence indicates a shortfall.

The action an establishment will be required to make following the identification of a shortfall is based on the HTA's assessment of risk of harm and/or a breach of the Human Tissue Act 2004 (HT Act) or associated Directions.

### **1. Critical shortfall:**

A shortfall which poses a significant risk to human safety and/or dignity or is a breach of the HT Act or associated Directions

*or*

A combination of several major shortfalls, none of which is critical on its own, but which together could constitute a critical shortfall and should be explained and reported as such.

A critical shortfall may result in one or more of the following:

- A notice of proposal being issued to revoke the licence
- Some or all of the licensable activity at the establishment ceasing with immediate effect until a corrective action plan is developed, agreed by the HTA and implemented.
- A notice of suspension of licensable activities
- Additional conditions being proposed
- Directions being issued requiring specific action to be taken straightaway

### **2. Major shortfall:**

A non-critical shortfall that:

- poses a risk to human safety and/or dignity, or
- indicates a failure to carry out satisfactory procedures, or
- indicates a breach of the relevant Codes of Practice, the HT Act and other relevant professional and statutory guidelines, or

- has the potential to become a critical shortfall unless addressed

*or*

A combination of several minor shortfalls, none of which is major on its own, but which, together, could constitute a major shortfall and should be explained and reported as such.

In response to a major shortfall, an establishment is expected to implement corrective and preventative actions within 1-2 months of the issue of the final inspection report. Major shortfalls pose a higher level of risk and therefore a shorter deadline is given, compared to minor shortfalls, to ensure the level of risk is reduced in an appropriate timeframe.

### **3. Minor shortfall:**

A shortfall which cannot be classified as either critical or major, but which indicates a departure from expected standards.

This category of shortfall requires the development of a corrective action plan, the results of which will usually be assessed by the HTA either by desk based review or at the time of the next inspection.

In response to a minor shortfall, an establishment is expected to implement corrective and preventative actions within 3-4 months of the issue of the final inspection report.

### **Follow up actions**

A template corrective and preventative action plan will be sent as a separate Word document with both the draft and final inspection report. Establishments must complete this template and return it to the HTA within 14 days of the issue of the final report.

Based on the level of the shortfall, the HTA will consider the most suitable type of follow-up of the completion of the corrective and preventative action plan. This may include a combination of

- a follow-up inspection
- a request for information that shows completion of actions
- monitoring of the action plan completion
- follow up at next routine inspection.

After an assessment of the proposed action plan establishments will be notified of the follow-up approach the HTA will take.